



COMPRA-VENTA DE MAQUINARIA
www.maquinariazubizarreta.com

Bench nut driver /

Capabilities

Machine type:	AUTOMATIC
Operating mode:	MANUAL/AUTOMATIC
Strain:	400 VOLT
Frequency :	50 Hz
Power absorbed:	2 Kw
Minimum nut dimensions:	1/2"
Maximum nut dimensions:	1"
Minimum threading:	67-60 mm
Maximum threading:	208 mm
Supply pressure:	6-8 bar
Cylinders:	SMC
Three-phase motors:	Minimotor
PLC:	SIEMENS S7
Cycle time:	8.5 sec.
Production changeover time (1 person):	+/- 15 min.
Maximum dimensions of the assembled delivery:	3900x2220x2400H mm
Phonometry	78 dBA

COMPRA-VENTA DE MAQUINARIA
www.maquinariazubizarreta.com

FOTOS / PHOTOS





COMPRA-VENTA DE MAQUINARIA
www.maquinariazubizarreta.com

FOTOS / PHOTOS



COMPRA-VENTA DE MAQUINARIA
www.maquinariazubizarreta.com

FOTOS / PHOTOS



COMPRA-VENTA DE MAQUINARIA
www.maquinariazubizarreta.com

FOTOS / PHOTOS

